Educational Suitability and Facility Condition Assessment



Facility Summary

Langford Elementary School, serving an enrollment of approximately 500 students in southeast Austin, is a neighborhood school built in 1980 with additions occurring in subsequent years. The building is approximately 58,000 square feet and sits on 1 acres. The learning spaces are set up in pods o the main corridor grouping six studios in a pod. In the center of each pod are the restrooms, a multipurpose room, storage and workroom. The gym and cafeteria can open into one space for larger events.

Building Address: 2206 Blue Meadow Austin, TX 78744


Building Square Footage: 57,700 SF Site Acreage: 10 Acres Date of First Construction: 1980

Student Demographics:

	Demographic	Percentage
) 1(os	African American	6.4%
	Hispanic	89.7%
	White	2.2%
	American Indian	0.0%
	Asian	0.8%
) Paci c Islander	0.0%
	Two or More Races	1.0%
	Economically Disadvantaged	95.2%
	English Language Learners	56.1%
	Special Education	16.1%
	Enrollment	503

Educational Suitability Assessment Score:

– – District ElementarySchool's ESA Average: 64



Very Unsatisfactory 0-35

Unsatisfactory 36-50

Average 51-65

Satisfactory 66-80

Very Satisfactory 81-100

Facility Condition Assessment Score:

--- District ElementarySchool's FCA Average: 62



Questions/Comments?

Email: Assessments@perkinswill.com

Langford Elementary School

Educational Suitability and Facility Condition Assessment

